

Oil Field Environmental Incident Summary

Incident: 20141113161613 **Date/Time of Notice:** 11/13/2014 16:16

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL 40-1509H

Field Name: PARSHALL

Well File #: 27037

Date Incident: 11/13/2014 **Time Incident:** 08:00

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 15

Qtr: SE SW

Location Description:

Submitted By: Keith Kallberg

Received By:

Contact Person: Keith Kallberg
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2.5	Barrels	2.5	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low

Areal Extent:

South of the treater on the other side of the trunk line 20 x 40 ft.

Potential Environmental Impacts:

Low

Action Taken or Planned:

Well was shut in and the valve was changed out. Hydro excavator used to remove the free fluid and affected material from inside the containment. Outside containment area was remediated onsite by raking and dragging.

Wastes Disposal Location: Fluids and solids to Newalta disposal at New Town ND.

Agencies Involved: TAT and MHA

Updates

Date: 11/14/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the boundaries of the MHA Nation. Forwarded to BIA/Tribal authorities.